

**SPINELLI**
LACHINE**Spinelli Mazda**230 Boul Montreal-Toronto
Lachine
H8S 1B8**1 581 703-8460****Make / Model**

Lexus IS 300

Year

2017

Mileage indicated / actual***102,208 km****Transmission**

automatic

Drive Type

AWD

Engine

6 cyl. / 3.5 liters

Fuel Type

unleaded

Serial number**Stock number**

240293A

**EQUIPMENTS**

Adaptive cruise control, Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Power locks, Power Mirrors, Power driver seat, Power sliding doors, Power steering, Power windows, Remote Entry, Adjustable steering wheel, Driver airbag, Fog lights, Passenger airbag, Rear defrost, Lateral airbags, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Sunroof, Two-toned paint, AM/FM stereo, Bluetooth, MP3 Player, Satellite radio, Bucket seats, Split folding rear seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Leather seats, Power passenger seat, Rear head air bag, Front floor mats, Anti-theft system, Brake assist, Auxiliary audio input, Universal garage door opener, Keyless entry, Auto-on headlights, Keyless start, Audio steering controls

SALE PRICE**\$27,038**

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

Category

Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:

As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:

A ☐ 6 months or 10 000 km B ☐ 3 months or 5 000 km C ☐ 1 month or 1 700 kmD ☐ Good working (subject to 37, 38 L.P.C.) E ☐ No warranty**Repairs done and mechanical verification certificate****Comments**

The following repairs have been done on this vehicle since the dealer's possession.

If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.

Optional repairs

The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Date : _____ Signature : _____

autoExpert.ca

Sticker # : 8329827