Date :

Spinelli Mazda

230 Boul Montreal-Toronto Lachine H8S 1B8

1 581 703-8460

Make / Model Mazda CX9 GSL Mileage indicated / actual* Year 2021 48.245 km **Transmission Drive Type** automatic **AWD Engine Fuel Type** 4 cyl. / 2.5 liters unleaded Serial number Stock number P9329



EQUIPMENTS

SALE PRICE

Adaptive cruise control, Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Power locks, Power Mirrors, Power driver seat, Power sliding doors, Power steering, Power windows, Rear A/C, Remote Entry, Adjustable steering wheel, Heated steering, Driver airbag, Passenger airbag, Rear defrost, Lateral airbags, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Sunroof, Two-toned paint, AM/FM stereo, Bluetooth, MP3 Player, Bucket seats, Split folding rear seats, 3rd row, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Leather seats, Power passenger seat, Rear head air bag, Front floor mats, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Keyless start, Power liftgate, Remote trunk release, Audio steering controls, Automatic wipers, Back windshield

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:
	A 6 months or B 3 months or C 11 month or 5 000 km C 1700 km
	D Good working E No warranty
Repairs done and mechanical verification certificate Comments	
The following repairs have been done on this vehicle since the dealer's possession.	
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.	
Optional repairs	
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :	

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8360418